

# ***Town of Copake Highway Department***

*230 Mt. View Road, Copake, New York 12516*

*William H. Gregory Jr., Superintendent  
Town of Copake Highway Department  
[copakehighwaydepart@yahoo.com](mailto:copakehighwaydepart@yahoo.com)  
[www.Copake.org](http://www.Copake.org)*

*Phone: 518-325-4222*

*Fax: 518-325-4151*

*Cell: 518-669-6161*

## ***Highway Department June 2015 Monthly Report:***

*We continued the annual cleaning of the ditches on our gravel roads. After the ditches are cleaned of debris and reshaped to carry rain runoff, we grade, gravel and apply liquid calcium to the road surface.*

*Roads worked on were: High Valley, Valley View, Tompkins, Maple Lane, Bain, Old 22 and Lakawanna*

*Repainted the Crosswalks on Mt. View and Lakeview Roads*

*We continued road side mowing*

*We hauled road materials from Hudson to the Highway Garage stockpile in anticipation of summer road work*

*The Highway Crew participated in the OSHA training provided by the Columbia County Highway Superintendents Association*

*Spent one day blacktop drag boxing Cambridge Rd*

*Spent one day chipping downed tree limbs following a heavy wind/rain storm*

*Spent two days cutting limbs on Cambridge Rd*

*Installed 250 feet of underdrainage on Sunset Rock Rd*

*Inter-departmental assistance the Highway Department provided included:*

### *Town:*

*We put up and took down the hamlet American Flags for Flag Day  
Pressure washed the Town Hall and Park Building*

### *Park:*

*Moved the Summer Program storage box from West Copake to the Park  
Assisted in the startup of the water chlorination system  
Repaired the overhead door in the Park garage*

*Inter-municipal Cooperation included:*

### *Town of Hillsdale*

*We borrowed their loader with a side dump bucket for two days while installing underdrainage*

***Town of Ancram***

***We supplied them with a truck for two days hauling blacktop***

***Taconic Hills Central School District:***

***We buried a water line for them***

***Copake Fire Company:***

***Repaired the mud flap on 14-6***

***Replaced the auto eject plug on 14-1***